



Detail of fiberglass hull repair, port side



Dense very small diameter (3/8-inch) osmotic blisters, sporadically throughout wetted surface hull



Spurrs line cutter on propshaft needs zincs.



Cosmetic fairing cracking around propshaft strut



Compass void of fluid and cover shot



All running rigging shot



Deck detail.



Windlass foot switches missing



Many exposed toe rail plank fasteners exposed



Hand rails thinned, fasteners exposed



Portlight screens shot



Mainsheet traveler bent upwards gently from loading. May be OK.



Engine instrument panel and cover to be replaced



Vintage, sun damaged electronics ondeck



Battery boxes and old battery cables



Water damaged minor bulkhead at forward end of port cockpit locker



Water damage in quarterberth cabin. All soft goods should be replaced due to mildew/mold



Water damaged wood around all portlights



Main salon table



Vintage ripped upholstery



Water damaged cabin sole veneer



Starboard side main salon



Corrosion at base of main mast



Walter vee-drive missing



Mildew on vinyl panelboard headliner



Dinette area